Public Works and Utilities Committee Meeting November 4, 2024


# Guadalupe Street Reconstruction Project An Update


Romella Glorioso-Moss, PhD, CPM
Complete Streets Capital Projects Manager

**Kody Keelin Project Manager I** 

#### THE PROJECT


#### Guadalupe Street – from Agua Fria to Paseo de Peralta





#### **ROAD SAFETY AUDIT RESULTS**


- 1) High occurrence of sideswipe crashes
- 2) Lack of Access Control
- 3) Insufficient geometrics/ poor intersection sight distance
- 4) Insufficient lighting
- 5) Substandard/Antiquated Traffic Signal Hardware/Design
- 6) Upgrades needed at Guadalupe St/Paseo de Peralta
- 7) Insufficient signage/striping/marking maintenance
- 8) Pedestrian issues ADA non-compliance, narrow sidewalks, obstruction in sidewalks
- 9) Noncompliance with posted speed limits
- 10) Corridor not multi-modal/poor/lack of transit, transit stops, poor pedestrian facilities, no dedicated bicycle lanes.



#### PROJECT-CHARACTERISTICS



#### From 25 mph to 20 mph






#### **ADA Compliant**

- All sidewalks at least 6'wide
- Curb ramps updated
- Obstructions eliminated
- Uneven surface eliminated

#### PROJECT CHARACTERISTICS



5'-wide bike lanes on both sides of the street

Continues raised median with occasional breaks to permit left turns

11 drive pads reconstructed

#### **PROJECT** CHARACTERISTICS



DE VARGAS ST / AGUA FRIA ST





**ALAMEDA ST** 

Eliminate EB Right-Turn Lane



Close Median



Pedestrian Phase



**JOHNSON ST** 



**Left-Turn Bay** 

MCKENZIE ST / JEFFERSON ST



PARK AVE / CATRON ST



Add Median & Left-Turn Bay

JOSE ST



**Full Access** 

**SOLONA ST** 




Right-In/Right-Out/Left-Out


**PASEO DE PERALTA** 



#### PROJECT CHARACTERISTICS



**GREEN INFRASTRUCTURE** 



- Sidewalk on the west side would be completely finished within 2 weeks
- New streetlights on the west side installed
- New storm drain pipes installed along with new drop inlets
- New electric meters installed
- New mast arms installed
- Started patching the asphalt along the entire section so they can start moving the traffic to the west side of the road to start work on the east side







**BEFORE** 



Storm water drainage infrastructure.

**Street lights replaced.** 





**BEFORE** 

**AFTER** 


**Electric meters replaced.** 



Intersection improvements
– mast arm pole base foundation



Storm
drain pipes
are
corroded












Sidewalks had no foundation creating sinkholes.

An acequia on the west side of Guadalupe St that runs from Johnson St to Paseo de Peralta was discovered

Kept running into existing utilities that needed to be relocated, replaced or repaired, such as the leaking gas main.



Business owners who are dissatisfied due to loss of income or opportunity.





Road users navigating traffic controls or through construction site.

## Public Engagement Activities (2015-

- 1) SFMPO created a video on the importance of the project
- 2) Conducted 3 public meetings between 2017-2022
- 3) Negotiated with all business owners for right-ofway acquisitions
- 4) Door hangers with all contact information
- 5) Advertises in 3 radio stations
- 6) Contractor and City Staff work with all businesses

#### **OUR PARTNERS**







NMDOT





# THANK YOU

Any questions?

rsglorioso-moss@santafenm.gov kwkeelin@santafenm.gov